



CENTERING INDICATOR




2385-3



- Provides quick and accurate centering in boring and milling set-up
- Maximum speed is recommended not to exceed 800rpm



Feeler	Measuring diameter	Accuracy
P1	$\varnothing 0-60\text{mm}$	0.015mm
P2	$\varnothing 0-160\text{mm}$	0.02mm
P3	$\varnothing 0-250\text{mm}$	0.03mm
P4	$\varnothing 3.2-80\text{mm}$	0.015mm
P5	$\varnothing 3.2-180\text{mm}$	0.02mm
P6	$\varnothing 3.2-280\text{mm}$	0.03mm
P7	$\varnothing 0-2.8\text{mm}$	0.015mm



Code

2385-3