








2846-3D

if the probe is pressed too much, the probe breaks at the breaking point, in order to prevent damage of the main body







- Shockproof, IP65 dust/waterproof
- Mainly used for milling machines and CNC machine tools
  - 1. determine coordinate point on workpieces
  - 2. find center of holes
  - 3. adjust and position workpieces
- Can be used to measure length and depth
- Reading shows movement value of probe.
  for example, if probe moves 0.01mm, reading changes 0.01mm
  Large working range on three axes (X, Y, Z),
- which avoids damage of probes due to collision by mistake
- Optional accessory: probe (code **2840-N1**)

Code	Range	Resolution	Repeatability at zero (one direction)	X, Y, Z range
2846-3D	±2mm	0.005mm	±0.005mm	6mm






## length measurement



## depth measurement



## position workpieces

