




# QUICK POSITIONING CONCENTRICITY GAGE

to ensure the accuracy  $2\mu\text{m}$ , the distance between measuring point and roller should be  $<30\text{mm}$



QUICK-POSITIONING, SUITABLE FOR MASS MEASUREMENT



4732-25

- Quick positioning, suitable for mass measurement
- Optional accessory: dial test indicators



Code	Diameter range	Workpiece length	Accuracy	Center height (h)	L×W×H	Weight
4732-25	$\varnothing 0.5\text{-}25\text{mm}$	15-100mm	$2\mu\text{m}$	70mm	267×120×147mm	5.5kg