

Spare parts for 3D tester 2842



Part NO.	Code	Description
1	SP-POINTER-2842-1	Pointer for 2842-3D
2	SP-BEZEL-2887	Bezel
3	SP-ADJUST SCREW-2842	Adjustable screw for 2842-3D